A-5885 Special Permit

Demolish the detached garage in the north (rear) yard.

William Curtin, III 3 Primrose Street

3 Primrose Street



Figure 1: 3 Primrose Street



Figure 2: View of the detached garage looking east



Figure 3: View of detached garage looking northwest.




Figure 4: View of the detached garage looking west.

CHEVY CHASE VILLAGE NOTICE OF PUBLIC HEARING

Please take notice that the Chevy Chase Village Board of Managers will hold a public hearing on the 11th day of April, 2011 at 7:30 p.m. The hearing will be held at the Chevy Chase Village Hall at 5906 Connecticut Avenue in Chevy Chase, Maryland.

APPEAL NUMBER A-5885 MR. WILLIAM CURTIN, III 3 PRIMROSE STREET CHEVY CHASE, MARYLAND 20815

The applicant has filed a request for a special permit pursuant to Section 8-11 of the Chevy Chase Village Code to demolish the detached garage in the north (rear) yard.

The Chevy Chase Village Code § 8-19 states:

Any person intending to demolish, raze or tear down more than fifty (50) percent of the exterior features of an existing building, garage or accessory building within the Village must first obtain a special permit from the Board of Managers for such demolition to ensure that such work will be carried out in such a manner that abutting property owners will not be adversely affected and that the interests of the Village in public health, safety and welfare are not jeopardized by such work.

Additional information regarding this case may be obtained at the Chevy Chase Village Office between the hours of 9:00 a.m. and 5:00 p.m. Monday through Friday, may be viewed on the Village website at www.chevychasevillagemd.gov or you may contact the office for this information to be mailed to you.

This notice was mailed to abutting property owners on the 1st day of April, 2011.

Chevy Chase Village Office 5906 Connecticut Avenue Chevy Chase, Maryland 20815 301-654-7300

MAILING LIST FOR APPEAL A-5885

MR. WILLIAM J. CURTIN, III 3 PRIMROSE STREET CHEVY CHASE, MD 20815

| Ms. Nancy B. Stone & | Mr. & Mrs. Jeff Black |
|---------------------------|---------------------------|
| Mr. Chuck Miller | Or Current Resident |
| Or Current Resident | 4 Quincy Street |
| 2 Quincy Street | Chevy Chase, MD 20815 |
| Chevy Chase, MD 20815 | |
| Ms. Jeanne Ruesch | Mr. & Mrs. Alan B. Geller |
| Or Current Resident | Or Current Resident |
| 1 Primrose Street | 5 Primrose Street |
| Chevy Chase, MD 20815 | Chevy Chase, MD 20815 |
| Mr. & Mrs. Edward McReady | Mr. & Mrs. Clarke Camper |
| Or Current Resident | Or Current Resident |
| 4 Primrose Street | 6 Primrose Street |
| Chevy Chase, MD 20815 | Chevy Chase, MD 20185 |

I hereby certify that a public notice was mailed to the aforementioned property owners on the 1st day of April, 2011.

Ellen Sands

Permitting and Code Enforcement Coordinator

Chevy Chase Village

5906 Connecticut Avenue

Chevy Chase, MD 20815



March 31, 2011

Mr. William J. Curtin, III 3 Primrose Street Chevy Chase, MD 20815

Dear Mr. Curtin:

Please note that your request for an appeal to demolish the detached garage on your property is scheduled before the Board of Managers on Monday, April 11, 2011 at 7:30 p.m.

Either you or another representative must be in attendance to present your case. At that time, additional documents may be introduced and testimony can be provided in support of the request.

Please note that because your property is located in the Chevy Chase Village Historic District, should the Board approve your request you will need to obtain a Historic Area Work Permit from the Historic Preservation Commission for the demolition of the garage as well as a Montgomery County demolition permit before the Village's Permit will be issued.

For your convenience, enclosed please find copies of the Public Hearing Notice and mailing list. Please contact the Village office in advance if you are unable to attend.

Sincerely,

Ellen Sands

Permitting and Code Enforcement

Chevy Chase Village

Enclosures

Chevy Chase Village

Application for a Special Permit

Chevy Chase Village Code Section 8-1(aa) defines a Special Permit as permission granted by the Board of Managers in accordance with Article II Division B of this Chapter [8], to construct, install, remove or alter a structure or planting, or take other action where such permission is required by this Chapter.

| | Subject Property: 3 PRIMROSE STREET, CHEVY CHRSE VILLAGE Describe the Proposed Project: Demolish the existing 20.1' x 18.3' gauge and remove a portion of the concete briveway that leads to the garage. Applicant Name(s) (List all property owners): WILLIAM J. CURTIN III Daytime telephone: 202.637.6418 Cell: 202.257.6600 E-mail: William. Curting hogan lovells-com Address (if different from property address): |
|--|--|
| | For Village staff use: Date this form received: $3 21 11$ Special Permit No: $A - 5885$ |
| Ellen Sands Ellen Sands Ellen Sands | Filing Requirements: Application will not be accepted or reviewed until the application is complete Completed Chevy Chase Village Application for a Special Permit (this form) Completed Chevy Chase Village Building Permit Application A boundary survey or plat diagram with a margin of error of one tenth of a foot or less showing all existin structures, projections and impervious surfaces. Surveys, plats, engineering reports, construction plans/specifications or other accurate drawings showin boundaries, dimensions, and area of the property, as well as the location and dimensions of a structures/fences/walls/etc., existing and proposed to be erected, and the distances of suc structures/fences/walls/etc., from the nearest property lines. These drawings shall incorporate and display reference dimensions from the boundary survey or plat diagram required above. Copy of Covenants, except for special permits authorized by Sections 8-22, 8-26 or Article IV of Chapter of the Chevy Chase Village Code. Applicable special permit fee listed in Chapter 6 of the Village Code. |
| | Affidavit I hereby certify that I have the authority to submit the foregoing application, that all owners of the property have signed below, that I have read and understand all requirements and that I or an authorized representative will appear at the scheduled public hearing in this matter. I hereby authorize the Village Manager, or the Manager's designed and/or the Board of Managers to enter onto the subject property for the purposes of assessing the site in relation to this special permit request. I hereby declare and affirm, under penalty of perjury, that all matters and facts set forth in the foregoing application are true and correct to the best of my knowledge, information and belief. Applicant's Signature. Date: March 21 2071 |
| | Applicant's Signature: Date: |

Describe the basis for the special permit request (attach additional pages as needed):

| Describe the reasons why approval of the s | pecial permit would not advers | sely affect the public health, safety or |
|---|---------------------------------|--|
| welfare or the reasonable use of adjoining p | properties: | |
| Demolition of the garage | - and removal of por | thon of contierers developer |
| will be done in decards | ince with all had | rable Chen Chan Villy |
| and Morkoney County Co | des and ordinaries | and mould as in |
| accordance with all demoliti | in semite and 13to | vie trea Worke Remist is incl |
| in Connection with the referen | ced project. | |
| | | |
| Describe the reasons why the special per | rmit can be granted without | aulastantial immailment Culture |
| purpose of Chapter 8 of the Chevy Chase V | fillage Code, entitled Ruilding | substantial impairment of the intent and |
| Grafing Her Second leven | | the without or mysone ? |
| Clarate & O Mary Chara Clara | 1431/4. (a). here | Market Planter Comment |
| nehit chrolle deto | 10 2 has | and the spring solo not |
| a costa se de la secono | 1-1-6 | and de hore was confue |
| to contribute to the historic | district you remain | el 1 le carge tenace 1 |
| govern of the consider dive | way mill be an | migrapement to the projects |
| | V | |
| In exercising its powers in connection with | a special permit request, the | Chevy Chase Village Board of Managers |
| may reverse or affirm, wholly or partly, o | or may modify the requiremen | nt, decision or determination as it deems |
| appropriate. | | |
| | | |
| | | |
| | | |
| | | |
| Special Description | CI I D II T | |
| Special Permit Filing Fees | Checks Payable To: | Chevy Chase Village |
| Timing Pees | | 5906 Connecticut Ave. Chevy Chase, MD 20815 |
| Per Village Code Sec. 6-2(a)(24): | | Chevy Chase, Wib 20013 |
| | | |
| \$300.00 for new construction. | Date Paid: 3211/ | |
| \$150.00 for replacing existing non-conformities. | | |
| \$2,250.00 for demolition of main | Staff Signature | |
| building. | Staff Signature: | |
| \$300.00 for demolition of accessory | 911. A. 16 | |
| building or structure. | mound | |
| \$300.00 for fences, walls, play | | |

equipment, trees, hedges, shrubbery in the

public right-of-way.

Fee Paid: 300 . 0

Chevy Chase Village

Building Permit Application

| Property Address: 3 Prime & Street |
|---|
| Cherry Chase May and 20815 |
| Chary Chase Maryland 20815 Resident Name: WILLIAM J. CURTIN III |
| Daytime telephone: 202. 637. 6418 Cell phone: 202. 257. 6600 |
| After-hours telephone: 202.257.6600 |
| E-mail: william. curting hoganlovelk. con |
| Provided Description |
| Denolish the existing 20.1' by 18.3' garge and |
| remove a partier of the concrete driveway that leads to the |
| garge. |
| Check here if the construction will require the demolition of over fifty (50) percent of any existing structure. |
| Primary Contact for Project: |
| Resident Architect Project Manager Contractor* |
| *MHIC/MD Contractor's License No. (required): |
| Information for Primary Contact for Project (if different from property owner): |
| Name: |
| Work telephone: After-hours telephone: |
| Cell phone: |
| E-mail: |
| |
| Will the residence be occupied during the construction project? |
| If no, provide contact information for the party responsible for the construction site (if different from above): |
| Name: |
| Address: |
| Work telephone: After-hours telephone: |
| Cell phone: |
| E-mail: |
| Parking Compliance: |
| Is adequate on-site parking available for the construction crews? |
| If no, please attach a parking plan which minimizes inconvenience to neighboring residents, and indicate if the property is in a permit parking area. |
| Will road closings be required due to deliveries, equipment or other reasons? |

Permit No: <u>A</u>-5885

Building Permit Filing Requirements: Application will not be reviewed until the application is complete

| Copy of stamped drawings approved by Montgomery County Department of Permitting Services (DPS) and the Historic Preservation Commission (HPC), if required. Every page of drawings must be clearly stamped. |
|---|
| This application form, signed by resident. |
| Boundary Survey |
| Site Plan (see: Village Site Plan Checklist to ensure completeness) |
| Building plans and specifications |
| Tree Preservation Plan requested of Village arborist (see: Village Tree Inspection Request form). All required tree protections must be fully installed before any work begins. N/A - & 3/20 11 |
| Filing Fee (due at time of application). Fees schedule is listed in Chapter 6 of the Village Code. |
| Damage deposit or performance bond (due when Building Permit is issued). Amount of required deposit or bond will be set by Village Manager. |
| Once this permit application is complete, the Village Manager will review the application and accompanying documents and, under most circumstances, act on the application within 5 to 10 working days. |
| If the Montgomery County permit is suspended, revoked or lapsed, the Village permit is automatically suspended, revoked or lapsed. |
| No signs advertising the architect, contractor, or any other service provider may be posted on the work site. |
| I hereby certify that I have the authority to make the foregoing application, that the application is correct, that I have read and understood all requirements and that the construction will conform to the regulations of the Montgomery County Zoning Code, the Village Code including Urban Forest code, and any covenants and easements on the subject property. Applicant's Signature: Date: Mach 21, 2511 |
| To be completed by Village staff: |
| Is this property within the historic district? Yes No Staff Initials: 28 Date application filed with Village: 311 Date permit issued: Expiration date: |

| For Use By Village Manager | Application approved wit | h the following conditions: |
|--|-------------------------------------|---|
| | | |
| | | |
| | | |
| - | | |
| For Use By Village Manager | Application denied for | the following reasons: |
| | Onoxo2600V | pecial parmit |
| MAR 2 1 RECD | required purs | upent to |
| Chevy Chase | Dec. 8,19 of Un | e Village Code. |
| Village Manager | | |
| Filing Fees (due when application submitted) | Checks Payable to: | Chevy Chase Village |
| (due when application sublitted) | | 5906 Connecticut Ave. Chevy Chase, MD 20815 |
| Permit Application Fee: \$ 100,00 (see Permit Fee Worksheet) | | |
| Tree Preservation Plan Fee: | | |
| Not required for this project. | | |
| TOTAL Fees: | Date: 3/18/11 Staff Signature: Ward | and |
| Damage Deposit/Performance Bone (due when permit is issued) | Checks Payable to: | Chevy Chase Village 5906 Connecticut Ave. Chevy Chase, MD 20815 |
| S Waived by Village Manager | Date: Staff signature: | |
| Cost of damage to R-O-W: (calculated at close-out) Amount of refund: | Date: Staff signature: | |
| | | |
| For Village Staff use: | | |
| Field file for inspections by Code Enforce | ement Officer has been created: | Yes (Date:) |

CCV Permitting

From:

Fothergill, Anne [Anne.Fothergill@mncppc-mc.org]

Sent:

Thursday, March 24, 2011 12:12 PM

To: Cc: CCV Permitting Curtin, William J.

Subject:

3 Primrose

hi Ellen,

This was approved last night:


3 Primrose—garage demo, new garage, fence/stucco wall, tree removal, and alterations and addition to house

I know the owner needs to come to the Village soon so I wanted to let you know (and he is copied on this email).

Thanks, Anne

Anne Fothergill
Planner Coordinator
Functional Planning and Policy Division | Historic Preservation Section
Maryland-National Capital Park and Planning Commission
301-563-3400 phone | 301-563-3412 fax

http://www.montgomeryplanning.org/historic
1400 Spring Street, Suite 500 W
Silver Spring, MD 20910



CAS ENGINEERING



BUILDERS OF QUALITY HOMES SINCE 1908

March 23, 2011

Chevy Chase Village 5906 Connecticut Avenue Chevy Chase, Maryland 20815

Tel: 301-654-7300 Fax: 301-907-9721

ccv@montgomerycountymd.gov

Re: Means and methods for demolition and removal of garage construction material at 3 Primrose Street, Chevy Chase, Md 20815

To Whom It May Concern:

Demolition and removal of construction material will at all times be done in accordance with all applicable Chevy Chase Village and Montgomery County codes and ordinances, as well as in accordance with the requirements of any permits, including demolition permits and Historic Area Work Permits issued in conjunction with said work.

- Prior to star of demolition, Gruver Cooley Corporation will prepare the site and install all sediment and tree protection required.
- Prior to commencing demolition activities, the garage will be hosed down in order to minimize any dust resulting from the demolition and water will be used as required and as needed throughout the demolition process.
- A licensed, EPA certified contractor will use a rubber tire excavator and power tools to demolish the existing garage. Debris will be loaded into 10 ton dump truck or dumpster that will be delivered to the appropriate landfills (for recycling) outside of the Village of Chevy Chase. The dumpsters will be placed on the existing driveway and hauled out Primrose Street to Connecticut Ave. until all material is removed.
- Work crews will make every attempt to park on private property and if needed will park in front of the house on Primrose.
- The demolition will take two days weather permitting.

The demolition of the existing garage at 3 Primrose Street will not affect the health, safety or welfare, or the reasonable use of adjoining properties. Granting of the Special Permit will not impair the intent or purpose of Chapter 8 of the Chevy Chase Village code.

Sincerely,

Clifton R. Gruver, Jr.

Gruver Cooley Corporation



Country Termite & Pest Control

P.O. Box 2082 Purcellville, VA 20134-2082 540-338-9018 (fax)

540-338-7821 888-909-7378 304-725-4489

March 23, 2011

TO: Gruver & Cooley Construction

RE: Rodent Certificate

To Whom It May Concern:

Country Termite & Pest Control monitored the garage at 3 Primrose Street in Chevy Chase, Maryland for rodents from March 15, 2011 through March 22, 2011. We found no activity of any rodents during this time.

Country Termite & Pest Control herby certifies that the garage at 3 Primrose Street in Chevy Chase, Maryland is free and clear of rodents as of March 22, 2011.

If you have any questions or concerns please feel free to give me a call.

Sincerely

Willie Grey Owner



15850 Crabbs Branch Way Suite 200 Rockville, MD 20855 Telephone: 301-417-0200 Facsimile: 301-975-0169

March 28, 2011

Mr. Chip Gruver Gruver & Cooley Construction 106 Loudoun Street, SW Leesburg, Virginia 20175

Re: Limited Asbestos Bulk Sampling and Lead-Based Paint-Chips

3 Primrose Court Chevy Chase, Maryland Apex Job No.: 11580.007

Dear Mr. Gruver:

On December 21, 2010 and March 23, 2011, Apex Companies, LLC (Apex) performed a limited asbestos containing bulk sampling and lead-based paint (LBP)-chip sampling within the residence and the garage at 3 Primrose Court in Chevy Chase, Maryland.

Apex performed limited bulk sampling of suspect asbestos containing plaster within the residence and the garage. Also, suspect asbestos containing window glazing and lead containing paintchips were sampled within the garage. The asbestos and LBP bulk sampling was conducted by an accredited AHERA/ASHARA Building Inspector and State of Maryland Lead Inspector Technician.

A total of twenty six (26) bulk samples of five (5) types of materials were collected for laboratory analysis within the residence and the garage area. Bulk samples collected on December 21, 2010 were analyzed at Scientific Analytical Institute, Inc (SAI) located in Greensboro, North Carolina. Bulk samples and paint-chips collected on March 23, 2011 were analyzed at EMSL Analytical, Inc. (EMSL) located in Beltsville, Maryland. Both laboratories are accredited by the American Industrial Hygiene Association (AIHA), and the National Voluntary Laboratory Accreditation Program (NVLAP).

Federal and State of Maryland regulations define a building material to be an asbestos containing material (ACM) if the material contains greater than one (>%1) percent asbestos by weight. Laboratory analysis of all of the bulk samples collected determined that no asbestos was detected in the 2-coat plaster and the window caulking.

Moreover, federal and State of Maryland define lead-based paint being greater than 0.5% lead by weight to determine whether LBP is present. The following components were found to contain lead in quantities exceeding the federal and State of Maryland criteria of >0.5%:

Exterior Brown Window Casing and Interior White Window Casing in the garage area.

Mr. Chip Gruver Gruver & Cooley Construction March 28, 2011 Page 2

The following components were found to contain lead in quantities that do not exceed the federal and State of Maryland criteria of >0.5 %:

 Interior White Wall, Exterior Light Brown Wall, Interior White Glass Painted and Exterior Dark Brown Window Sill.

Enclosed please find a copy of the laboratories reports of bulk sample analysis and the LBP – chips results.

Apex appreciates the opportunity to be of service to Gruver & Cooley Construction in this matter. If you have any questions or comments, please call me.

Sincerely,

Apex Companies, LLC

Indira S. Mendez
Industrial Hygienist

Maryland Division

Reviewed by,

Scott W. McAllister

Senior Project Manager

Maryland Division

Enclosure



EMSL Analytical, Inc.

307 West 38th Street, New York, NY 10018

Phone: (212) 290-0051

Fax: (212) 290-0058 Email: manhattanlab@emsl.com

Attn: Apex Companies, LLC 15850 Crabbs Branch Way Suite 200

Rockville, MD 20855

Customer ID:

APEX52

Customer PO:

03/25/11 10:33 AM

Received: EMSL Order:

031108199

Fax:

(301) 975-0169

Phone: (301) 417-0200

Project: **BID 945** EMSL Proj:

Test Report: Lead in Paint Chips by Flame AAS (SW 846 3050B*/7000B)

| Client Sample Description | Lab ID | Collected | Analyzed | Lead Co ncentration |
|---------------------------|-------------|-------------|-----------------|-------------------------------|
| PB1 | 0001 | 3/23/2011 | 3/25/2011 | 0.018 % wt |
| Si | te: INTERIC | R WHITE W | ALL | 3.0.0 % |
| PB2 | 0002 | 3/23/2011 | 3/25/2011 | 11 % wt |
| Si | te: EXTERIO | OR BROWN V | VINDOW CASING | 77 70 110 |
| PB3 | 0003 | 3/23/2011 | 3/25/2011 | 0.71 % wt |
| Si | te: INTERIO | R WHITE WI | NDOW CASING | |
| PB4 | 0004 | 3/23/2011 | 3/25/2011 | 0.069 % wt |
| Si | te: EXTERIO | OR LIGHT BR | OWN WALL | 7 |
| PB5 | 0005 | 3/23/2011 | 3/25/2011 | 0.23 % wt |
| Si | te: INTERIO | R WHITE 9H | RS PAINTED | |
| PB6 | 0006 | 3/23/2011 | 3/25/2011 | 0:11 % wt |
| Si | te: EXTERIO | OR DARK BR | OWN WINDOW SILL | 3.77 77 110 |

Initial report from 03/25/2011 17:41:10

Miron Apfeldorfer, Laboratory Manager or other approved signatory

M. Apteldorfer

Reporting limit is 0.01 % wt. The QC data associated with these sample results included in this report meet the method quality control requirements, unless specifically indicated otherwise. Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities.

* slight modifications to methods applied Samples received in good condition unless otherwise noted. Quality Control Data associated with this sample set is within acceptable limits, unless otherwise noted

Samples analyzed by EMSL Analytical, Inc. New York, NY AIHA-LAP, LLC-ELLAP Lab 102581, NYS ELAP 11506



EMSL Analytical, Inc. Relinquish Form

| Initial Lab: | EMSL- | Beltsville | | Phone Number: | 301-937-57 | 00 | | |
|---|--|-----------------|---|---------------------|--|--|---|---------|
| | | | | Fax | 301-937-57 | 01 | | |
| | | | | Number: | | | *************************************** | |
| Relinquished to: | EMSL- | , | | Phone | | | | |
| | m | w hatte | | Number: | | | | |
| | | 44 r house | ou. | Fax Number: | | | | |
| Does new Lab ho | ld equival | ent or ado | litional acci | | VYes [| No | | |
| EMSL Customer | ID#: | * | | | | | *************************************** | |
| Client Name: | The state of the s | 400 | × Oppo | panies | navaranteen een maanapaningen een augustus een augustus een augustus een augustus een augustus een augustus ee | | *************************************** | |
| Client Ducinet | | INFC | r Com | yemies. | f* | | wings a first state a constitution of the first state and the state and the state and the state and the state a | |
| Client Project: | | BID. | 145 | | | | * | |
| Date Received: | | 3/24 | 111 | | | | | |
| Date Relinquishe | d: | 3/2 | 3/11 | | | | | |
| Date Due: | | 3/25 | 5/11 | | | | | |
| Special Instructio | ns: | | and the second second second second second second | | | (Sciolis) (Collections | | |
| Relinquished by (Signat | ure); | Date: | | y (Signature) | 2 | | Date: 3/15 | 1033 |
| Relinquished by (Signat | ure): | Date: | Received b | y (Signature) | tantan magamatan kanan dan menangkan dan sebagai dan sebagai dan sebagai dan sebagai dan sebagai dan sebagai d | | Date: | |
| Client Notification- Plea laboratory to relinquish | se sign this fo | orm and fax to | o the original lab | ooratory. By sign | ing below you ag | ree to allo | ow the above na | med |
| Name (please Print) | are samples to | Signatu | | | ntof: | The second secon | Date: | |
| Spe attack | | noil | from (| ·lientA | | University of the section of the sec | | |
| If this is a reoccurring processing the laboratory will keep this | roject or samp | ole type that v | vill require samp | les to be relinquis | shed on a regular | basis ple | ase sign below a | ind the |
| iaporatory will keep this | form on file. | | | | ntof: | | Date: | |

031108199



Lead (Pb) Chain of Custody

EMSL ANALYTICAL, INC. 10768 BALTIMORE AVE BELTSVILLE, MD 20705 PHONE: (301) 937-5700 FAX: (301) 937-5701

| , , | Orialli of Guotous |
|---------|------------------------|
| EMSL Or | der ID (Lab Use Only): |
| | C100 |
| K) < 1 | 108199. |
| | 20111 |

| Street: 15850 Crabbs Branch way | | | | | | If Bill to is [| Different not | e instruc | tions in Comn | nents** | | |
|---|---|--|---|---|---------|---|--|---|---|--------------|---|-----------|
| Street: 15 | 150 Cabbs | Branch | way | | | Third Pa | ty Billing | requires w | ritten au | ıthorization | from th | ird party |
| City: boc | avilla | St | tate/Pro | vince: | 1 | Zip/Postal Code: Country: | | | | | | |
| Report To (Name): Sm (Allister) apex cos. com | | | | | 1 | Fax #: | | | - Contraction | | | |
| Telephone #: | | • | 7. | ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | | Email Add | iress: / | mende | 22 | apex c | · 20 | con |
| | /Number: BID. | 945 | *************************************** | ······································ | | *************************************** | | | and the same | , | | |
| | | | | Purchase | Order: | | | U.S. Sta | te Sar | nples Tak | en: | |
| Please Provide Results: Fax Email Purchase Ord Turnaround Time (TAT) Op | | | | | | s* - Plea | se Che | MARKET MARKET THE PARTY OF THE | | <u> </u> | | |
| 3 Hours | 6 Hours | 24 Hours | | 48 Hours | | Days | 4 | | | 5 Days | | 10 Days |
| LJOHOGIS | *Analysis | completed in ac | cordance | | | | ns located | d in the Pri | ce Guio | le | | |
| | Matrix | | | Method | | In | strume | nt | Rep | orting Li | mit | Check |
| | ng/cm² % by wt. | | | 46-7000B/742 40AC 974.02 | 0 | Flame / | Atomic Ab | sorption | | 0.01% | | 12 |
| Air | | | N | IIOSH 7082 | | Flame | Atomic Ab | sorption | | 4 μg/filter | | |
| | | - | N | IIOSH 7105 | | Grap | nite Furna | ce AA | 0 | .03 µg/filte | er | |
| | | | NIOS | H 7300 modifi | ed | | ICP-AES | | C | .5 µg/filte | r | |
| Minet E | CTM | | | 46-7000B/742 | | Flame | Atomic Ab | sorption | - | 0 µg/wipe | | |
| Πn | STM on ASTM | ļ | | | | Flame | ICP-AES | | | .5 µg/wip | **** | [[] |
| *if no box is chec | cked, non-ASTM Wipe is | assumed | | 346-6010B or | | Flores | Atomic Ab | | | mg/L (pp | MARKET MARKET AND THE | |
| TCLP | | | | 311/7420/SM 346-6010B or | | Flame | ICP-AES | | | mg/L (pr | | |
| Call | | | | W846-7420 | 0 | Flame | Atomic Ab | | ORGANIZATION | mg/kg (pr | | |
| Soil | | | SW846-7421 | | | Graphite Furnace AA | | | 0.3 mg/kg (ppm) | | | |
| | | - | SW86-6010B or C | | | ICP-AES | | | 1 mg/kg (ppm) | | | |
| Wastewater | | | | SM3111B or | | Flame | Atomic Ab | sorption | - 0.4 | mg/L (pr | m) | |
| Wastewater | | | SW846-7000B/7420 EPA 200.9 | | 20 | Graphite Furnace AA | | 0.003 mg/L (ppm) | | | | |
| | | | | 346-6010B or | С | 1 | ICP-AES | | | ng/kg (pp | | |
| Drinking Wa | ater | | | EPA 200.9 | | Grap | hite Furna | ice AA | | 03 mg/L (p | | |
| Other: | | | | | Pres | ervation | Method | i (Wa to r | 1.7 | | | |
| | mpler: Indian | 5 Mg | ENDE | 2 | Sign | ature of | Sample | r: A | 50 | Ma | 2 | 2 |
| Sample # | Tipler. Trendi | Location | | | T Cigii | | Volume | | | | | Sampled |
| | 71. | | J | | | *************************************** | SHED | | | | , | |
| P61 | Interior Exterior | | | | 10 | | L | | | | | |
| 963 | | inite | Ľ | 4 | 1 | *************************************** | 1 | | | | *************************************** | |
| P64 | Exterior L | | | | | | 1 | | *************************************** | | www.iess.reeacovo.et | |
| PSJ | Interior w | | | | / | | 1 | | | | | |
| P66 | | Dark Brow | | | | ., | 1 | | | | | |
| Client Samp | | - Pb | 6 | | | | Tota | al # of S | ample | es: 4 | S | |
| Relinquishe | 1 | DIM S ME | | Date: | 03/ | 23/20 | N | Time: | | 12:3 | 07 | m |
| Received (La Comments: | b): | KOSWOLLK | 0 | Date: | 3/ | 24/11 | ······································ | Time: | - | 9:5 | 5a | er |
| Comments: | 2 · · · · · · · · · · · · · · · · · · · | Lee | ACX | | | 1 | LAIR | mns | | V 2 | 2/ | 5 10:3 |
| *************************************** | ~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~ | ###################################### | | | | 611) | 107 |) vas | 1 | , we | 11 | 2 10- |



Bulk Asbestos Analysis

By Polarized Light Microscopy EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: Apex Companies, LLC

15850 Crabbs Branch Way

Suite 200

Rockville, MD 20855-2622

Project: G&C Primrose Street

Attn: Scott McAllister

Adam Truax

Lab Order ID:

1015019

Analysis ID:

1015019PLM

Date Received:

12/22/2010

Date Reported: 12/22/2010

| Sample ID | Description | Asbestos | Fibrous | Non-Fibrous | Attributes | | |
|---------------|----------------------------|---------------|------------------|-------------|---------------------------------------|--|--|
| Lab Sample ID | Lab Notes | Aspestos | Components | Components | Treatment | | |
| PL-1-B1 | Beige skim coat | None Detected | | 100% Other | Beige Non Fibrous Heterogeneous | | |
| 1015019PLM_1 | | i | | | Crushed | | |
| PL-1-B2 | Beige skim coat | None Detected | | 100% Other | Beige Non Fibrous Heterogeneous | | |
| 1015019PLM_2 | | | | | Crushed | | |
| PL-1-B3 | Beige skim coat | None Detected | | 100% Other | Beige Non Fibrous Heterogeneous | | |
| 1015019PLM_3 | | | , and the second | | Crushed | | |
| PL-1-B4 | Beige skim coat | None Detected | | 100% Other | Beige Non Fibrous Heterogeneous | | |
| 1015019PLM_4 | | | wi | | Crushed | | |
| PL-1-B5 | Beige skim coat | None Detected | | 100% Other | Beige Non Fibrous Heterogeneous | | |
| 1015019PLM_5 | | | 2 | | Crushed | | |
| PL-1-B6 | Beige skim coat | None Detected | | 100% Other | Beige Non Fibrous Heterogeneous | | |
| 1015019PLM 6 | | | | | Crushed | | |
| PL-1-B7 | Beige skim coat | None Detected | | 100% Other | Beige Non Fibrous Heterogeneous | | |
| 1015019PLM_7 | | | | | Crushed | | |
| PL-2-B8 | White plaster beneath PL-1 | None Detected | 2% Cellulose | 98% • Other | White Non Fibrous Heterogeneous | | |
| 1015019PLM 8 | | | | | Crushed | | |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommended that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Estimated MDL is 0.1%.

Dorlos Ammerman (21)

Nathaniel Durham, MS or Approved Signatory

Scientific Analytical Institute, Inc. 302-L Pomona Dr. Greensboro, NC 27407 (336) 292-3888



Bulk Asbestos Analysis

By Polarized Light Microscopy EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: Apex Companies, LLC

15850 Crabbs Branch Way

Suite 200

Rockville, MD 20855-2622

Project: G&C Primrose Street

Attn: Scott McAllister

Adam Truax

Lab Order ID:

1015019

Analysis ID:

1015019PLM

Date Received:

12/22/2010

Date Reported:

12/22/2010

| Sample ID | Description | Asbestos | T | Fibrous | N | on-Fibrous | Attributes | | |
|------------------------------------|---------------------------------|---------------|----------|-------------------------------|-----|------------|---------------------------------------|--|--|
| Lab Sample ID | Lab Notes | Aspestos | | Components | C | omponents | Treatment | | |
| PL-2-B9 White plaster beneath PL-1 | | None Detected | 2% | Cellulose | 98% | Other | White Non Fibrous Heterogeneous | | |
| 1015019PLM_9 | | * (| | | (9 | | Crushed | | |
| PL-2-B10 | White plaster beneath PL-1 | None Detected | 2% | Cellulose | 98% | Other | White Non Fibrous Heterogeneous | | |
| 1015019PLM_10 | | | | | | | Crushed | | |
| PL-2-B11 | White plaster beneath PL-1 | None Detected | 2% | Cellulose | 98% | Other | White Non Fibrous Heterogeneous | | |
| 1015019PLM 11 | | | | | | | Crushed | | |
| PL-2-B12 | White plaster beneath PL-1 | None Detected | 2% | Cellulose | 98% | Other | White Non Fibrous Heterogeneous | | |
| 1015019PLM_12 | | | | | | | Crushed | | |
| PL-2-B13 | White plaster beneath PL-1 | None Detected | 2% | Cellulose | 98% | Other | White Non Fibrous Heterogeneous | | |
| 1015019PLM_13 | | | | | | | Crushed | | |
| PL-2-B14 | White plaster beneath PL-1 | None Detected | 2% | Cellulose | 98% | Other | White Non Fibrous Heterogeneous | | |
| 1015019PLM_14 | | | | | à. | | Crushed | | |
| PL-3-B15 | Gray/brown plaster beneath PL-2 | None Detected | 3% 3% | Cellulose Synthetic Fibers | 94% | Other | Brown Non Fibrous Heterogeneous | | |
| 1015019PLM_15 | | | | | | | Crushed | | |
| PL-3-B16 | Gray/brown plaster beneath PL-2 | None Detected | 5% 5% | Cellulose Synthetic Fibers | 90% | Other | Brown Non Fibrous Heterogeneous | | |
| 1015019PLM_16 | | | | | . 4 | | Crushed | | |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommended that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Estimated MDL is 0,1%.

Dorlos Ammerman (21)

Analyst

Nathaniel Durham, MS or Approved Signatory

Scientific Analytical Institute, Inc. 302-L Pomona Dr. Greensboro, NC 27407 (336) 292-3888



Bulk Asbestos Analysis

By Polarized Light Microscopy EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: Apex Companies, LLC

15850 Crabbs Branch Way

Suite 200

Rockville, MD 20855-2622

Project: G&C Primrose Street

Attn: Scott McAllister

Adam Truax

Lab Order ID:

1015019

Analysis ID:

1015019PLM

Date Received:

12/22/2010

Date Reported: 12/22/2010

| Sample ID Description | | Asbestos | Fibrous | Non-Fibrous | Attributes |
|-----------------------|---------------------------------|-----------------------------------|----------------------------------|-------------|---------------------------------------|
| Lab Sample ID | Lab Notes | Aspestos | ASDESTOS Components | | Treatment |
| PL-3-B17 | Gray/brown plaster beneath PL-2 | None Detected | 5% Cellulose 5% Synthetic Fib | 1 | Brown Non Fibrous Heterogeneous |
| 1015019PLM_17 | | | | | Crushed |
| PL-3-B18 | Gray/brown plaster beneath PL-2 | None Detected | 5% Cellulose 5% Synthetic Fib | 90% Other | Brown Non Fibrous Heterogeneous |
| 1015019PLM_18 | | | | | Crushed |
| PL-3-B19 | Gray/brown plaster beneath PL-2 | None Detected | 3% Cellulose 3% Synthetic Fib | 94% Other | Brown Non Fibrous Heterogeneous |
| 1015019PLM_19 | | eli, a aast jedis oo oming om laa | | | Crushed |
| PL-3-B20 | Gray/brown plaster beneath PL-2 | None Detected | 5% Cellulose 5% Synthetic Fib | 90% Other | Brown Non Fibrous Heterogeneous |
| 1015019PLM_20 | | | | | Crushed |
| PL-3-B21 | Gray/brown plaster beneath PL-2 | None Detected | 5% Cellulose 5% Synthetic Fib | 90% Other | Brown Non Fibrous Heterogeneous |
| 1015019PLM_21 | | | | | Crushed |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommended that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Estimated MDL is 0.1%.

Dorlos Ammerman (21)

Nathaniel Durham, MS or Approved Signatory

Scientific Analytical Institute, Inc. 302-L Pomona Dr. Greensboro, NC 27407 (336) 292-3888

240-876-2519 ADAM



Scientific Analytical Institute 302-L Pomona Dr. Greensboro, NC 27407 Phone: 336.292.3888 Fax: 336.292.3313 www.sailab.com lab@sailab.com

| 16 | 1 | Z | 50 |) | 9 | ì |
|------------------------------|--------|------------|------|-----|---|---|
| Lab Use Only | | | | | | |
| Lab Order II Client Code: |): | hil. Mi | | | | |
| | | | JAN. | ħħ. | | |

| Company Conf | act Information | | | | Asbestos Test Typ | ies |
|--|-------------------|---------------|----------------------------|---------|-----------------------------|------------|
| Company: APEX (| | Contact: Adam | Truax | | PLM EPA 600/R-93/116 | |
| | Crabbs Branch Way | Phone □: 301 | | | Positive stop | > |
| Suite 2 | , | Fax [: 301- | 975-0169 | | PLM Point Count | |
| Rockville | , MD. 20855 | Email : SMC | Uax Wapexcos | .com | PCM NIOSH 7400 | (day) |
| 100 11/12 | , | 57 | MILITAN COMPEN | <u></u> | TEM AHERA | |
| Billing/Invoice | Information | Turn A | round Time | S | TEM Level II | |
| Company: APEX | | 90 Min. | 48 Hours | | TEM NIOSH 7402 | |
| Contact: Scott | | 3 Hours | 72 Hours | | TEM Bulk Qualitative | |
| Address: 15850 (| Crabbs Branch Way | 6 Hours | 96 Hours | | TEM Bulk Chatfield | |
| Suite & | | 12 Hours |] 120 Hours [| | TEM Bulk Quantitative | |
| Rockvil | le MD. 20855 | 24 Hours |] 144 ⁺ Hours [| | TEM Wipe ASTM D6480-99 | . 🗆 |
| | | | | | TEM Microvac ASTM D5755-02 | · 🗆 |
| | ID. 945 | | | | TEM Water EPA 100.2 | |
| Project Name/Nu | mber: 6 + C Prim | rose Street | • | | Other: | |
| - B2 - B3 - B4 - B6 - B6 - B7 PL-2 - B8 - B10 - B11 - B12 - B13 - B14 | White Plaster 1 | beneath PL- | 2 | | Adam Truax of Scott McAllis | |
| | | | | | Total # of Samples | 21 |
| Relinq | uished by D | ate/Time | Rede | iyed b | | Section of |
| adam Tru | | 121/10 | ALL | 19 | W 1232 | P |
| Scientific Analytical Institu | ute | Δ | ccepted [| / | Pageof | a |

Rejected



Scientific Analytical Institute 302-L Pomona Dr. Greensboro, NC 27407 Phone: 336.292.3888 Fax: 336.292.3313 www.sailab.com lab@sailab.com

| | 0 | / | 5 | \bigcirc | / | 9 |
|------------------------------------|--------|---|---|------------|---|---|
| Lab Use (Lab Orde Client Co | er ID: | | | | | |

| Sample ID # | Description/Location Gray/Brown Plaster beneath PL-2 | Volume/Area Comments |
|-------------|--|----------------------|
| PL-3-B15 | Gray Brown Plaster Leneath PL-2 | |
| - B16 | | |
| - 1317 | | |
| -318 | | |
| - B20 | | |
| -320 | | |
| V - B21 | 1 | 1 |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| × 2 | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | * | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | Page 2 of 7 |



EMSL Analytical, Inc.

10768 Baltimore Avenue, Beltsville, MD 20705

Fax: (301) 937-5701 Email: <u>beltsvillelab@emsl.com</u> Phone: (301) 937-5700

Attn: Scott McAllister

Apex Companies, LLC

15850 Crabbs Branch Way

Suite 200

Rockville, MD 20855

Fax:

(301) 975-0169

Project: BID 945

Phone: (301) 417-0200

EMSL Proj:

Customer ID:

Customer PO:

EMSL Order:

Received:

Analysis Date:

3/24/2011

191102738

APEX52

03/24/11 9:55 AM

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| | | | | Non-Ast | pestos | <u>Asbestos</u> |
|--|--|--|----|-------------|--|-----------------|
| Sample | Description | Appearance | % | Fibrous | % Non-Fibrous | % Type |
| 03232011 ISM B1 191102738-0001 | WHT WINDOW CAULKING - EXT WINDOW | Gray/White Non-Fibrous Heterogeneous | | | 100% Non-fibrous (other) | None Detected |
| 03232011 ISM B2 191102738-0002 | WHT WINDOW CAULKING - EXT WINDOW | Gray/White Non-Fibrous Heterogeneous | | | 100% Non-fibrous (other) | None Detected |
| 03232011 ISM B3- Top - Rough coat plaster 191102738-0003 | PLSTR - THROUGHOUT SHED | Brown/Gray/Yellow Fibrous Heterogeneous | 5% | o Cellulose | 40% Non-fibrous (other) 50% Quartz 5% Mica | None Detected |
| 03232011 ISM B3- Bottom - Concrete material 191102738-0003A | PLSTR - THROUGHOUT SHED | Brown/Gray/Beige Non-Fibrous Heterogeneous | 70 | | 45% Non-fibrous (other) 55% Quartz | None Detected |
| 03232011 ISM B4- Top - Rough coat plaster 191102738-0004 | PLSTR - THROUGHOUT SHED | Brown/Gray/Yellow Fibrous Heterogeneous | 5% | o Cellulose | 40% Non-fibrous (other) 50% Quartz 5% Mica | None Detected |

| Initial report from 03/24/2011 13:19:19 | |
|---|--|
| Analyst(s) | Jugh Centiforte |
| George Malone (8) | Joe Centifonti, Laboratory Manager or other approved signatory |

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Samples analyzed by EMSL Analytical, Inc. Beltsville, MD NVLAP Lab Code 200293-0



EMSL Analytical, Inc.

10768 Baltimore Avenue, Beltsville, MD 20705

Fax: (301) 937-5701 Email: beltsvillelab@emsl.com Phone: (301) 937-5700

Attn: Scott McAllister

Apex Companies, LLC 15850 Crabbs Branch Way

Suite 200

Rockville, MD 20855

(301) 975-0169

Project: BID 945

Fax:

Phone: (301) 417-0200

EMSL Proj:

Customer ID:

Customer PO:

EMSL Order:

Received:

Analysis Date:

3/24/2011

APEX52

191102738

03/24/11 9:55 AM

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| | | | | Non-A | sbestos | Asbestos |
|--|-------------------------------|---|----|-------------|--|---------------|
| Sample | Description | Appearance | % | Fibrous | % Non-Fibrous | % Type |
| 03232011 ISM B4- Bottom - Concrete material 191102738-0004A | PLSTR - THROUGHOUT SHED | Brown/Gray/Beige Non-Fibrous Heterogeneous | | | 45% Non-fibrous (other) 55% Quartz | None Detected |
| 03232011 ISM B5- Top - Rough coat plaster 191102738-0005 | PLSTR - THROUGHOUT SHED | Brown/Gray/Yellow Fibrous | 3% | o Cellulose | 42% Non-fibrous (other) 5% Mica 50% Quartz | None Detected |
| 03232011 ISM B5- Bottom - Concrete material 191102738-0005A | PLSTR - THROUGHOUT SHED | Brown/Gray/Beige- Non-Fibrous Heterogeneous | | | 45% Non-fibrous (other) 55% Quartz | None Detected |

| nitial report from 03/24/2011 13:19:19 | |
|--|--|
| Analyst(s) | Juga Centifords |
| George Malone (8) | Joe Centifonti, Laboratory Manager or other approved signatory |

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Samples analyzed by EMSL Analytical, Inc. Beltsville, MD NVLAP Lab Code 200293-0



| EMSL | | • | 02738 | | | AODE | OTO C |
|--|-----------------|--|------------------|------------|---|--|--|
| ANALY | | CHA | IN OF CUST | ODY | <u></u> | ASBE | 5105 |
| • | nnie Frasca | | man Mili | | CAME | | |
| | ex Companies, | | EMSL-Bill to |): _ | SAME | | • |
| to the same of the | 850 Crabbs Brai | nch Way | Street: | | | | |
| | ite 200 | | Box #: | _ | | | Zip: |
| | ckville, MD | | 0855 City/State: | 4 | | | _ zih |
| | ACALLISTER OF | pex COS. Co | | | 301-975- | 0460 | |
| | 1-417-0200 | | Fax #: | | 301-910- | 0103 | |
| Project Name/Number: | BID . 945 | | Purchase 0 | | | Telegraph of the control of the cont | |
| MA MA | RIX. | | | | | OUND TIME | |
| ☐ Air ☐ Floor Tile | ☐ Soil ☐ | ☐ Wipe | (2) 6 Hours | | | 24 Hours | ☐ 48 Hours |
| 🔀 Bulk 🛘 Drinking Wate | r 🗆 Dust 🗀 |]Wastewater | 1 3 Days | □ 5 l | | ☐ 6-10 Days | ☐ Same Day*** |
| | | | 4 | **Musi | | | *** 10:00AM delivery results by Mid-night |
| and the second s | | | per acquest of | appro | | | or earlier |
| PCM | PLM BULK (reg | gular bulk) | TEM BULK | - FF | | TEM WATER | |
| □ NIOSH 7400 | EPA 600 | guiai bang | ☐ Drop Mount (C | Qualitativ | re) | ☐ Wastewat | er |
| □ OSHA | □ NOB | | ☐ Chatfield | | | | Nater EPA 100.1 |
| ☐ Other: | ☐ Point Coun | t | ☐ Chatfield / SE | M QC | | | Y Wastewater |
| TEM AIR | ☐ Other: | | ☐ Conventional | (Quantita | ative) | ☐ Water-NY | Drinking Water |
| ☐ AHERA | SEM | | ☐ EMSL Method | | | | |
| ☐ NIOSH 7402 | ☐ Qualitative | | L 1,00 | | | TEM WIPE | |
| □ Level I | ☐ Quantitativ | е | □ NOB / SEM QC | | | ☐ Quantitative | |
| ☐ Level II | | | I more the | | | ☐ Qualitativ | e |
| | | ······································ | ☐ Micro Vac - Q | | | | |
| XRD | OTHER | | Stop posi | Lus | ٠. | | |
| ☐ Asbestos | ☐ COMMENT | <u>S</u> | Stol Tones | 95000 | | | |
| ☐ Silica | B1 | | BJ | | | Samples: | |
| Client Sample # (s) | | 530 | Date: | 3/ 13 | 711 | Time: | 12:35 p.m |
| Relinquished: Foot | Bosilous | | | 3/24 | 111 | Time: | 9:55 alm |
| Received: | Florence | Jeck L | Date: | 1 1 | <i></i> | Time: | |
| | ENUMBIES . | | MATERIAL | | | | LOCATION |
| | | | | | | Fxt. a | vindowa (a) |
| 0323/2011 IM BL | | | ndow Coul | eing | | 4 | |
| 1 25M BZ | | 2 | L X | | | | |
| ISM B3 | | Plaster | | | | Through | wt shad |
| 25M 134 | | plasta R. | | | | 1 | |
| 1/25M B5 | | plaster. Plaster | | | | 1 | Į. |
| V 33.7 - | $\overline{}$ | | | | | | |
| |) | | $\overline{}$ | | | | |
| | / | | | | | | |
| | | | | | | | |
| | -) | | | 1 | | | |
| | / | | | | | | Andrew Control of the |
| | | | | | *************************************** | | |
| | | | | | | | |

Chevy Chase Village

Tree Inspection Request Form

| Property Address: |
|---|
| 3 Miniose |
| Date this form submitted to Village office: |
| Resident Name: |
| Phone: |
| E-mail: |
| This request initiated by: Village office staff. Resident/property owner |
| ☐ Inspect tree(s)¹ requested for removal are any of conditions in Village Code Sec. 17-3(a) met? ☐ Inspect trees¹ on property to determine if a Tree Protection Plan (TPP) is needed for proposed project². ☐ Pursuant to a Village Bldg Permit application², prepare TPP for trees¹ on property [\$250 fee] ☐ Verify that a TPP has been implemented for Village Building Permit # ☐ Follow up on an existing TPP is it OK to remove TPP? ☐ Village right-of-way/park ☐ Other: ☐ Show location of tree(s) on a plat or site plan (or on diagram on reverse, but only if plat unavailable). |
| ² Attach full description of proposed project. |
| Sections below must be completed by Village Arborist: |
| Tree #1: Private Property Village right-of-way Location: Rear Front Side-L Side-R DBH*= Species: Tag#: In/a: no tag Assessment: Assessment: Carflut with tree for Con |
| Tree #2: Private Property Village right-of-way |
| Assessment: |
| Tree #3: Private Property Village right-of-way |
| Assessment: |
| (For more trees, please check here and attach pages: # of extra trees; # of extra pages.) Arborist assessment: Does tree meet any of the conditions in Village Code 17-3 to qualify for removal? |
| Removal Approved Denied *Is permit required? (i.e, is trunk circumf. ≥24"?) Y N |
| Tree #1 Tree #1 |
| Tree #2 |
| Tree #3 |
| Arborist Signature Date 3-29 |



HISTORIC PRESERVATION COMMISSION 301/563-3400

APPLICATION FOR HISTORIC AREA WORK PERMIT

Contact Person: DAVID JONES Daytime Phone No.: 202-332 - 1200 Name of Property Owner: WILLIAM CURTIN Contractor Registration No.: Agent for Owner: DAVID JONES _____ Daytime Phone No.: 202-332-1200 COMMON OF BUILDING A BANKE Street PRIMROSE Nearest Cross Street CONN. AUE. 58 Subdivision: SECTION 2 SANTONIA TYPE DEPENDIT AMOUNT AND USE 1A. CHECK ALL APPLICABLE: CHECK ALL APPLICABLE: ☑ Room Addition ☐ Porch ☐ Deck ☐ Shed ☐ Move ☐ Install Single Femily Fenca/Wall (complete Section 4) Vother: GARAGE Revision Repair 1B. Construction cost estimate: \$ 1C. If this is a revision of a previously approved active permit, see Permit # SARTIMOR COMPUTEROR NEW CONSTITUCTION AND PARENDY ADDITIONS Type of sewage disposal: OI PWSSC 02 Septic 2B. Type of water supply: 01 DWSSC 02 U Well 03 🗌 Other: PANTHREE GOMPLETEDING FOR ESTABLISHING WALL 3B. Indicate whether the fence or retaining wall is to be constructed on one of the following locations: ☐ On party line/property line Entirely on land of owner I hereby certify that I have the authority to make the foregoing application, that the application is correct, and that the construction will comply with plans approved by all agencies listed and I hereby acknowledge and accept this to be a condition for the issuance of this permit. For Chairperson, Historic Preservation Commission Application/Permit No.:

SEE REVERSE SIDE FOR INSTRUCTIONS

Edit 6/21/99

THE FOLLOWING ITEMS MUST BE COMPLETED AND THE REQUIRED DOCUMENTS MUST ACCOMPANY THIS APPLICATION.

1. WRITTEN DESCRIPTION OF PROJECT

| | | NOTICE INSULTES I | | |
|------------------------------------|---|---|--|---|
| | house | in C | nevy Cha | se Village |
| · VAIICI. | | | | |
| project and its effect on the hist | oric resource(s), the envir | onmental setting, | and, where applicable, the | historic district: |
| existive | 1-500 | ry rec | ar addit | ion. |
| | project and its effect on the histandanal. NEW GARACE EXISTINE | project and its effect on the historic resource(s), the envir | project and its effect on the historic resource(s), the environmental setting, CANAGE. VEW GAYAGE. | project and its effect on the historic resource(s), the environmental setting, and, where applicable, the GANAGE. WEW GANAGE. 2. EXISTING 1-3TON REAN AGAIT |

2. SITE PLAN

Site and environmental setting, drawn to scale. You may use your plat. Your site plan must include:

- a. the scale, north arrow, and date;
- b. dimensions of all existing and proposed structures; and
- c. site features such as welkways, driveways, fences, ponds, streams, trash dumpsters, mechanical equipment, and landecaping.

3. PLANS AND ELEVATIONS

You must submit 2 copies of plans and elevations in a format no larger than 11" x 17", Plans on 8 1/2" x 11" paper are profesred.

- a. Schematic construction plans, with marked dimensions, indicating location, size and general type of walls, window and door openings, and other fixed features of both the existing resource(s) and the proposed work.
- b. Elevations (facades), with marked dimensions, clearly indicating proposed work in relation to existing construction and, when appropriate, context. All materials and fixtures proposed for the exterior must be noted on the elevations drawings. An existing and a proposed elevation drawing of each facade affected by the proposed work is required.

4. MATERIALS SPECIFICATIONS

General description of materials and manufactured items proposed for incorporation in the work of the project. This information may be included on your design drawings.

5. PHOTOGRAPHS

- a. Clearly labeled photographic prints of each facade of existing resource, including details of the affected portions. All labels should be placed on the front of photographs.
- Clearly label photographic prints of the resource as viewed from the public right-of-way and of the adjoining properties. All labels should be placed on the front of photographs.

6. TREE SURVEY

If you are proposing construction adjacent to or within the dripline of any tree 6" or larger in diameter (at approximately 4 feet above the ground), you must file an accurate tree survey identifying the size, location, and species of each tree of at least that dimension.

7. ADDRESSES OF ADJACENT AND CONFRONTING PROPERTY OWNERS

For ALL projects, provide an accurate list of adjacent and confronting property owners (not tenants), including names, addresses, and zip codes. This list should include the owners of all lots or parcels which adjoin the parcel in question, as well as the owner(s) of lot(s) or parcel(s) which lie directly across the street/highway from the parcel in question. You can obtain this information from the Department of Assessments and Taxation, 51 Monroe Street, Rockville, (301/279-1355).

DAVID JONES ARCHITECTS

1739 CONNECTICUT AVE. NW. WASHINGTON. DC 20009 FAX: 202-332-7044 TEL: 202-332-1200

16 December 2010

Historic Preservation Commission Maryland- National Capital Park and Planning Commission 8787 Georgia Avenue Silver Spring, MD 20910

Re:

Garage Removal 3 Primrose Street Chevy Chase, MD 20815

Dear Commissioners:

We are writing to support our client's wish to remove an existing garage located in the middle of his rear yard. We support this action based on the following considerations:

1. The garage is located in the center of the rear yard and does not allow for a private outdoor space suitable for a family to enjoy. To access the garage, there is a large paved turning area which takes up a significant portion of the property. The garage is only 5 feet off the back of the house, creating an awkward and dreary space on the north side of the house.

2. The garage is in poor condition. As shown in the attached photos, the garage has suffered termite and rot damage. The windows are broken with sills that are rotted. The structure is leaning toward the house, and is a hazard. A portion of the roof sheathing is damaged and the roof leaks. The garage passage door is warped and requires significant effort to open and close.

3. The garage has been altered from its original state. The garage door has been replaced with a metal overhead door with new aluminum siding above. Large sections of framing are new.

4. With the low-pitched roof form, the structure does not reflect the Tudor character of the main house.

In my professional opinion, this garage should not be considered a contributing resource to the property or the historic district. It is a purely utilitarian building that was to be hidden behind the house, away from view. It is too large to suit our client's needs and obstructs his enjoyment of the property. Its siting, condition, and scale make it a nuisance to the homeowner and affords nothing to the neighborhood.

Sincerely.

Enclosures

DAVID JONES ARCHITECTS

1739 CONNECTICUT AVE. NW. WASHINGTON. DC 20009 FAX: 202-332-7044 TEL: 202-332-1200

Curtin Residence 3 Primrose Street Chevy Chase MD 20815

Abutting and Confronting Properties:


Jeanne Ruesch 1 Primrose Street Chevy Chase, MD 20815


Alan & Sondra Geller 5 Primrose Street Chevy Chase, MD 20815

Carol & Edward McReady 4 Primrose Street Chevy Chase, MD 20815


Clark & Naomi Camper 6 Primrose Street Chevy Chase, MD 20815

Current Owner 4 Quincy Street Chevy Chase, MD 20815






Wooden Screen Wall with Brick Piers ELEVATION




Curtin Residence South Elevation with Proposed Brick Wall


N.T.S. Date: 1.51.2011




Brick Wall with 16" Columns And Wooden Gate ELEVATION Project: Curtin Date: 1.31.2011





SUBVEY CAS ENGINEERING




Curtin Residence . Site Flan 1"=20' . Dones Archts. 1.27-11












Cuntin Residence . West Education @ 16"=1:0". David downs Anchitects





. North Elevation e 16"-1:0" . David charle Anchitects 1-27-11 Curtin Residence





CURTIN RESIDENCE . GARAGE & 1/2" - DAVID JONES ARCHITECTS 1.27.11














EXISTING GARAGE - SCOTTH SIDE




EXISTING GARAGE . EAST SIDE




EXPTING GAPAGE - WEST SIDE




EXISTING GARAGE - NORTH SIDE




GARAGE & HOUSE




GARAGE LEANING.





GARAGE INTERIOR



ND

| | REFERENCES | |
|-------|------------|--|
| CTION | PLAT BK. | |



